

PECFA number: 54467-9999-00  
**BRRTS number: 03-50-000252**  
Site Owner: Village of Plover  
**Site Name:** Village of Plover Municipal Garage  
Site Address: 2300 Chestnut Drive, Plover WI 54467

Program contact: Dee Zoellner, Site Review Hydrogeologist  
Program contact address: 2129 Jackson St., Oshkosh WI 54901  
Program contact phone: 920-424-0046

### **Submitted Questions and Responses**

1. Only parts of the information on the groundwater investigation were provided. Will the remainder of the information be made available? When all the data was requested, this is what was sent to Commerce. **Additional data is available for review at the Wisconsin Rapids DNR office.**
2. In the October 1991 Lampert & Lee report, the installation of an in-site remediation system was recommended. Was the system ever installed? **Yes** If it was A) How long did it run, **3+ years** B) Does the system remain at the site, **No** C) When was it shut off?, **May 1995** D) How much water was recovered from the system? **Approximately 25 million gallons**
3. If the system wasn't installed, were the recovery well and vapor extraction wells put to use? If so, is there any data? **NA**
4. Did the site (i.e. building and sheds) undergo construction changes after the initial investigation? **Yes**
5. What is the status of the private wells located West and North of the site. Have the residences been connected to city water? Have the wells been abandoned? If not have they been sampled since 1981? **Municipal water is available but existing residences are not required to hook up to it. No known private wells were ever identified or sampled as part of the investigation by the consultant.**
6. Who owns the property to the west of the site? **The village owns the property immediately to the west of the former tank basin. Past that unknown**
7. Has groundwater flow consistently been to the northwest? **Yes, when the GWX system is not operating.**

8. Are there complete data tables which have historical groundwater quality and elevation data for all wells associated with the investigation? **There are elevation tables through '95 but there is no complete set of groundwater quality tables for all of the monitoring wells.** If not, have MW6, MW8 and MW5 historically been clean? **MW6 – The well was abandoned in '92 and could not find any lab data for this well; MW5 and MW8 - Yes**
9. Is there a complete Soil Quality table for all soil borings installed at the site? **No, the data is dispersed throughout the file.**
10. What will happen if the monitoring wells to be installed as part of Section 4 are impacted? **Remediation and/or closure must comply with NR700 Series** Will additional funding be available to define the extent of contamination? **Yes** Would changes in the remedial strategy be allowed if size information changed as a result of the additional wells installation (i.e. free product discovered or contamination extends across Chestnut Street) **Yes**